


# Insta-TEST<sup>®</sup> 6 Plus

50 Pool & Spa Test Strips

- FREE CHLORINE
- BROMINE
- TOTAL CHLORINE
- ALKALINITY
- pH
- TOTAL HARDNESS
- CYANURIC ACID

**LaMotte**  
Just DIP & READ!



Code 3028

Made in USA

Immerse strip for **2 SECONDS**. Remove with **pads face up**. **SHAKE ONCE TO REMOVE EXCESS WATER**. Read immediately: FCI>TCI>Alk>pH>TH>CyA

|   |     |     |     |     |      |      |
|---|-----|-----|-----|-----|------|------|
| <b>FCI</b><br>Free Chlorine ppm<br>(Br) Bromine ppm | 0   | 0.5 | 1   | 3   | 5    | 10   |
|   | (0) | (1) | (2) | (6) | (10) | (20) |

|                                  |   |     |   |   |   |    |
|----------------------------------|---|-----|---|---|---|----|
| <b>TCI</b><br>Total Chlorine ppm | 0 | 0.5 | 1 | 3 | 5 | 10 |
|----------------------------------|---|-----|---|---|---|----|

|                              |   |    |    |     |     |     |
|------------------------------|---|----|----|-----|-----|-----|
| <b>Alk</b><br>Alkalinity ppm | 0 | 40 | 80 | 120 | 180 | 240 |
|------------------------------|---|----|----|-----|-----|-----|

|           |     |     |     |     |     |     |
|-----------|-----|-----|-----|-----|-----|-----|
| <b>pH</b> | 6.2 | 6.8 | 7.2 | 7.8 | 8.4 | 9.0 |
|-----------|-----|-----|-----|-----|-----|-----|

Purple color indicates excessive sanitizer

|                                 |   |     |     |     |      |
|---------------------------------|---|-----|-----|-----|------|
| <b>TH</b><br>Total Hardness ppm | 0 | 100 | 250 | 450 | 800+ |
|---------------------------------|---|-----|-----|-----|------|

|                                 |   |    |     |     |     |
|---------------------------------|---|----|-----|-----|-----|
| <b>CyA</b><br>Cyanuric Acid ppm | 0 | 40 | 100 | 150 | 250 |
|---------------------------------|---|----|-----|-----|-----|

For best results, pH must be between 7.0-8.4

- Keep wet fingers out of the bottle.
- Close cap lightly after removing strip.
- In pools, immerse strip to a depth of 6".
- In spas, turn off jets and immerse strip to a depth of 6".
- For best results read in natural daylight.
- Store in a cool, dry place.



LaMotte Company, Chestertown, MD 21620 USA  
www.lamotte.com/insta